



Search over 57,700 items for sale...

Search

Browse by category ▼

Auctions ▼

How it works ▼

Financing

Home Page / Trucks & Trailers / Humvees / 2 Door Misc:

[Search for other Humvees items](#)



1987 AM General M1025 HMMWV 2 Door w/Truck Body

ITEM NUMBER	1399576
LOCATION	Yermo, California, United States. 92398
SOLD ON	6/27/18
WINNING BID	US \$7,600
# OF BIDS	21 View Bid History

SOLD!

ITEM DETAILS

MILEAGE	10,577 Miles
VIN	028XXX

Diesel Enigne, Automatic Transmission, 4x4, 8,200 lb. GVWR, 2 Door, Armament Carrier Body, 37x12.50R16.5 Tires. ***Buyer will need to complete and submit a Hold Harmless Agreement before scheduling pickup.***No further demilitarization is required. The HMMWV is available for pick up as shown.***



Inspected by IronPlanet.

Your purchase is protected by our **IronClad Assurance**.



[See Full Gallery](#) (101 - photos & videos)

[Print](#)
[Email](#)
[Shar](#)
[Shar](#)
[Shar](#)

Recommendations For You [Search all](#)



2005 AM General M1123 HMMWV 2 Door w/Truck
California (2,187 mi away)
US \$7,000



AM General M1123 HMMWV 2 Door w/Truck Body
California (2,187 mi away)
US \$6,500



AM General M1123 HMMWV 2 Door w/Truck Body
California (2,187 mi away)
US \$6,500



AM General M1123 HMMWV 2 Door w/Truck Body
California (2,187 mi away)
US \$6,500



AM General M1123 HMMWV 2 Door w/Truck Body
California (2,187 mi away)
US \$6,000



AM General M1123 HMMWV 2 Door w/Truck Body
California (2,187 mi away)
US \$6,500

Previously Viewed



AM General M1037 HMMWV 2 Door Hard Top w/Helmet
Virginia (83 mi away)
US \$5,600



AM General M1025 HMMWV 2 Door Soft Top w/Truck
California (2,187 mi away)
US \$10,100



2003 AM General M1045A2 HMMWV 4 Door Hard Top
Georgia (622 mi away)
US \$35,700

INSPECTION REPORT

General Appearance
Drivetrain

Control Station
Chassis

Engine
Logistics

Please note that as the buyer, you are responsible for reviewing the entire inspection report when evaluating an item.






IMPORTANT INFORMATION

Export Control Compliance
Payment Details
Questions


Manifest
Shipping & Pick Up Details

 Protected by IronClad Assurance®

GENERAL APPEARANCE

DESCRIPTION	RATING	DETAILS
Paint		
Sheet Metal Condition		
Mirrors		
Exterior Lights	Operational	
 (24)		

CONTROL STATION



NOTICES & RESTRICTIONS

This item is offered for **Off-Road Use Only**.

Buyer will be required to sign a **Hold Harmless Agreement**.

Buyer is required to submit an End-Use Certificate (EUC) to be reviewed prior to removal of the item. First-time buyers of Demil B,D,E,F,Q, OR C items may experience an extended review period in the Trade Securities approval process.

GovPlanet is only permitted to sell Demil B,D,E,F,Q, OR C items within the United States and only to U.S. citizens.

Security requirements and restrictions may apply at the time of pickup. **See shipping terms for details.**

Specific terms & conditions apply. **See details.**

Items may be subject to U.S. export controls. **See details.**














MANIFEST

NSN/LSN	Demil code ¹	Description (DTID) ✓
2320011077155	Q	HL000673390001

¹DLA Disposition Services Demilitarization Codes. Click on code for more information.



PAYMENT DETAILS

DESCRIPTION	RATING	DETAILS
Glass Condition		
Seating		
Seat Belts	Operational	
Steering Control		
Drivetrain Controls		
Master Cylinder/Brake Control		
Park Brake	Weak	
Limited Function Check - Brakes	The service brakes performed. The park brake would not hold the machine.	
Oil Pressure	Inoperable	
Warning Lights	Operational	
Gauges		
Odometer	10,577 miles - IronPlanet makes no guarantees as to actual hours/miles; we can only report what can be visually observed.	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	
 (20)		
ENGINE		

- Within **3 business days** after the auction, the buyer must submit full payment, including applicable taxes and fees to avoid **late fees**. For this item, payment is due on or before July 2.
- This item is subject to **California sales tax**.
- Buyer must pay a **transaction fee**, based on the final selling price:

FINAL SELLING PRICE	TRANSACTION FEE
Above \$1	10%

- Payment can be made by **wire transfer (recommended)** or credit card (**additional fee will apply**).
- If Selected, a Standard Form 97 (SF97) or Transferable titling document will be sent to the buyer by express mail or similar service. Typically buyers will receive their SF97 within 30 business days, although it can take up to 60 Business days, from the date the buyer takes possession of the item. Transferable titling documents typically take up to 30 business day after receipt of the SF97. Buyer is responsible for vehicle registration.
- **All bids are binding** and cannot be retracted. Failure to make full payment will result in a **Default Fee**.



SHIPPING & PICK UP DETAILS

- Buyer is **responsible for all costs** related to transporting the item.
- Item **must be picked up within 8 business days** of the auction, or the buyer will incur storage charges.

PICKUP TERMS

Failure to follow these terms may result in the seller turning away the attempt of your driver to pick up the purchased item(s).

Hours: All pickup times must be scheduled in advance with GovPlanet Customer Service.

Pickup times and requirements vary by location, all pickup times must be scheduled in advance with GovPlanet Customer Service.












No Loading Dock, Ramps, or Forklift Available: Only RGN or trailers with ramps can be used to pick up this item at this location. Seller will not allow item to be loaded on a step-deck or flatbed trailer without the appropriate ramps.

Driver **MUST** bring a copy of the IronPlanet Item Release to pick the item up.



QUESTIONS

Customer Care Agents are available Monday to Friday, 6 a.m. to 5 p.m. (Pacific Time)

DESCRIPTION	RATING	DETAILS
Emission Certification Label		Exempt 
Oil Pump/Tach Drive (behind doghouse cover)		
Blow by @ idle (subjective observation)	Minor	
Starter		
Fuel System		Operational; There is a leak around the fuel pipes. 
Exhaust System		
Radiator		
Oil Leaks		There is residue around the front of the engine. 
Fuel Leaks	None seen	
Cooling System Leaks	None seen	
Engine - Right Side		
Engine - Left Side		
Limited Function Check		The engine started and ran.
 (25)		
DRIVETRAIN		

Phone 888-433-5426
+1-925-225-8600 (outside U.S.)

Fax 888-433-3467
+1-925-225-8610 (outside U.S.)

Email CustomerCare@ironplanet.com

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.




DESCRIPTION	RATING	DETAILS
Transmission		
Transfer Case		
Steer Axle		
Rear Drive Axle		
Limited Function Check		The drivetrain was operational.



(14)

CHASSIS

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

DESCRIPTION	RATING	DETAILS
Steering Linkage		
Frame Condition		
Limited Function Check		The main chassis components functioned during a limited check.
Tire Condition		
Wheel Condition		
Wheel Studs, Nuts, Lugs		



(15)

LOGISTICS

DESCRIPTION	RATING	DETAILS
Shipping Dimensions - DLA		Length: 180"; Width: 86"
Machine Weight - DLA		Machine weight: 5820lbs

Disputes:

This item is offered with **IronClad Assurance®** protection. With IronClad Assurance®, if a buyer discovers that the item is not substantially in the condition as represented in this inspection report, the buyer may submit a written dispute claim to IronPlanet. Following submission of a written dispute claim, IronPlanet will investigate the claim, re-inspecting the equipment item as necessary, and determine a fair and mutually beneficial resolution. Please note that IronPlanet inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

 **Need help?** [Contact Us](#)

 **North America** ▾ **English** ▾

Company[About IronPlanet](#)[About Ritchie Bros.](#)[Careers](#)[Blog](#)[Terms & Conditions](#)[Privacy](#)[Site Map](#)**Support**[Contact Us](#)[How to buy](#)[How to sell](#)[FAQs](#)[RitchieSpecs](#)**Our family of sites**[GovPlanet](#)[TruckPlanet](#)[Asset Appraisal Services](#)[Kruse Energy](#)[Ritchie Bros. Auctioneers](#)[SalvageSale](#)[Mascus](#)**Popular categories**[Truck Tractors](#)[Crawler Dozers](#)[Dump Trucks](#)[Equipment Trailers](#)[Excavators](#)[Agricultural Tractors](#)[Flatbed Trucks](#)**Stay connected****Download Our Mobile App**

Copyright © 1999-2019 IronPlanet, Inc. All Rights Reserved. IronPlanet®, Asset Appraisal ServicesSM, TruckPlanet®, GovPlanet®, Kruse EnergySM, IronClad Assurance® and Auctions you can trust® are service marks of IronPlanet, Inc. All other marks and brands are the property of their respective owners.